ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W1227	NA	Agrahara lake road
Segment No.	**Total Length (m)**	
5/S-W1227/S072257	139.30	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	139.30	77.618276	13.089226	77.618420	13.090477	Agrahara lake road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and drains at Agrahara village Ashwathkatte opp road in ward no. 05 Byataryanapura sub division	2000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		005-18-000064
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/65/2018-19	24/07/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/07/2018	24/07/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
GOPIREDDY		0.00
Phone No.	**E-Mail ID**	
7760405418		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		mahantesh

Date of Inspection	Remarks
14/09/2018	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	parameshwaraiah r l	15/09/2018	14/10/2018	approved
SE	Vasu K M	15/09/2018	14/10/2018	Completed
EE	Mohandas H.T	14/09/2018	14/10/2018	completed
AEE	Sridhar	14/09/2018	14/10/2018	verify
AE	Mahantesh kumar	14/09/2018	14/10/2018	Mobile verification is done
AE	Y.N.Mahantesh Kumar	14/09/2018	14/10/2018	Forwarded